



Photo No. IMG\_1606; Taken on 01/19/14 at 11:00 hours by START MD. The contractor excavated a trench inside the wall of the containment area and discovered a compromised corrugated pipe that runs under the site.



Photo No. IMG\_1610; Taken on 01/19/14 at 11:05 hours by START MD. Contractors continue to pump water from the unknown source located just outside the containment wall.



Photo No. IMG\_1619; Taken on 01/19/14 at 11:16 hours by START MD. Standing at the corner of the containment wall, looking down at the Elk River, the trench is visible and has been extended to contain the newly discovered "seep."



Photo No. IMG\_1622; Taken on 01/19/14 at 11:16 hours by START MD. The trench at the northeastern end of the facility is currently successfully collecting the drainage from the containment area.